

# KUE KEN 120S

Complete refurbishment of primary jaw crusher.



International Crusher Solutions

Specialists in crusher wear parts & machinery.



120s Kue Ken being delivered to ICS





Damaged draw back bolts that we replaced. Sump plate bolts missing, we re-drilled and taped damaged holes and fitted new bolts c/w a new cover plate.





Work Starts Striping out hinge pin and eccentric shaft



Lifting Out Jaw Stock



# Jaw Stock Removed



### Jaw stock frame



Jaw stock hinge Pin bush totally worn away.



Hinge pin removed and inspected.



#### Damaged shaft to be replaced




New hinge pin bushes to be fitted to both sides of jaw stock.



New jaw stock hinge pin bush being fitted.



Bush Fitted Correctly



Both Bushes fitted and held with grub screws to ensure bush does not move.



Jaw stock checked and ready to be refitted.



New hinge pin ready to be fitted.



Fitting new hinge pin.




Swing jaw guide striped down for inspection.



No oil found.



New seal fitted to swing jaw guide.



Pump striped and cleaned with new gasket set.



Flywheel to be removed due oscillation movement.

After removing fly wheel bronze bush was found to be worn out.





## Damaged and worn flywheel bush

Pressing out worn bush

Fitting new bush to pulley.



Toggle and pitman before removal and inspection.



Bearings rusted and in poor condition due to lack of lubrication.



Damaged pitman shaft



Toggle Plates & Pin Removed





Removal of diaphragm and diaphragm frame.

Damaged diaphragm



#### Tapping holes out for toggle cover.



Re-tapping toggle cover plate holes to ensure the cover plate is sealed



Damaged diaphragm removed and diaphragm frame holes re-tapped.



New diaphragm fitted.



Pitman and toggles ready for installation.



Pitman toggles and toggle pin fitted.



Eccentric shaft and bearing assembly being fitted





New eccentric shaft bearing.

Pressing bearings into main frame.



New draw back rods and springs fitted



Kue Ken 120s- Fully refurbished being craned on to low-loader destination Africa